Schematic Symbol for XC2C256-VQ(G)100

The Orcad symbol consists of 2 heterogeneous parts, each of them listed below:

1. I/O Pins (BANK1 and BANK2)



Notes:
-GTS = global output enable, GSR = global reset/set, GCK = global clock, CDRST = clock divide reset, DGE = DataGATE enable.
-GTS, GSR and GCK pins can be used for general purpose I/O.

2. Power and Programming Interface



Document Revision History

	Revision	Date	By	Comments
1	1.01	Oct 5, 06	LD	Initial Release